











## Speed / Torque Curves

200V  
Single Phase



100V



**A : CONTINUOUS DUTY ZONE**

**B : INTERMITTENT DUTY ZONE**

\*The peak torque available for these motors with LEGEND AC amps and 100VAC Systems are shown in dashed lines. The Continuous Duty rating curve is the same as shown, except with speed limitations (up to the crossover point with derated Peak Torque Rating (dashed lines)).

\*\*The speed torque shown is applicable for either 200VAC Single-Phase or 200VAC Three-Phase