



M E 4 2 0 1 C W

Eff.	Watts	Volts	Amps	RPM
1.00 -	10000 -	100 -	100 -	10000 -
0.90 -	9000 -	90 -	90 -	9000 -
0.80 -	8000 -	80 -	80 -	8000 -
0.70 -	7000 -	70 -	70 -	7000 -
0.60 -	6000 -	60 -	60 -	6000 -
0.50 -	5000 -	50 -	50 -	5000 -
0.40 -	4000 -	40 -	40 -	4000 -
0.30 -	3000 -	30 -	30 -	3000 -
0.20 -	2000 -	20 -	20 -	2000 -
0.10 -	1000 -	10 -	10 -	1000 -
0.00 -	0 -	0 -	0 -	0 -



LBN