



ME1114 REV-A 022-CW 2014.06.06

Eff.	Watts	Volts	Amps	RPM
1.00-	10000-	100-	200-	5000-
0.90-	9000-	90-	180-	4500-
0.80-	8000-	80-	160-	4000-
0.70-	7000-	70-	140-	3500-
0.60-	6000-	60-	120-	3000-
0.50-	5000-	50-	100-	2500-
0.40-	4000-	40-	80-	2000-
0.30-	3000-	30-	60-	1500-
0.20-	2000-	20-	40-	1000-
0.10-	1000-	10-	20-	500-
0.00-	0-	0-	0-	0-



Torque (Lb. in.)



Note: This is a system plot. Input to control, output from motor.